

Cell Phone Support List

as of 2005-08-26

Note:The List is updated from time to time in our website. However, there are many discrepancies on cell phone's firmware version and the variations of supporting features for various regions. You may still see some glitches or incompatibilities on these phones. Please report the problem when you encounter one. We definitely will try best to solve the problem if possible. Occasionally, from any reason, we may have to apologize to drop the support of a particular phone form the list.

PHONES INTEROPERABILITY TESTED		
Manufacturer	Tested Models	Similar models supposed to work
Nokia	6600	
	7610	6670, 6670b
	6310i	
	6820	
	6230	
	N-Gage	
	6630	
	3230	
	9300	
Motorola	V551	
	V600	V500, V525, V80, E398, A630, 550, V535, V545, 550, V600i, V620,V330
	V710	
	V3	V551, V555
	A1000	
Sony-Ericsson	K700i	
	P900	
	T610	
	Z600	

	S700	S700i / S700c
	V800	
Siemens	SX1	
	U15	
	SX66	
Sharp	GX-T15	
Panasonic	EB-X70	X70/X88
Fujitsu	F900iT	
PalmOne	Treo 650	

Phone Characteristics

Phone specific behavior observed	Manufacturer	Model
1) Music will not resume after call terminates (feature of HV1 phone type)	Sony-Ericsson:	T610, Z600 BlackBerry: 7100t
2) Audio is not transferred to headphone after pressing the BT phone accept button. BT link between phone and UHS is disconnected while cellular phone call is still on.	Sony-Ericsson:	T68i, K700i, V800, P900, Z600; Panasonic: EB-X70
3) "Accept call from phone accept button" routes audio to Headphone ONLY if on the phone change "incoming Call" option "In hands Free" under Blue tooth manually.	Sony-Ericsson:	K700i, S700i
4) When phone call is disconnected from other side, notice "Music-mute-Music" cycle instead of clean transition to music.	Motorola:	E398, V600

5) Call must be picked up during a ring	Sony-Ericsson: T68i, S700i; Panasonic: EB-X70
6) Button Press sound on phone is not transferred to headphone	Sony-Ericsson: T610, T68i, P900, S700i, Z600; Panasonic: EB-X70
7) When receiving a call, the ring is not transferred to the headphone	Sony-Ericsson: P900
8) When receiving a call, the call can't be picked up at the first ring tone.	Nokia: 6230, 3230