

AirLive Security Gateway Firmware Release_IAR-5000

New Release: 9.02

Previous Release: 7.10

MD5 Checksums:

IAR-5000 : bb5a01657de4f763322ab91f9116ea5b

Note:

1. Verify the MD5 checksums of the downloaded file with a MD5 sum checker (e.g., MD5summer) to see if it matches the one provided above.
2. Please back up your system configuration prior to the upgrade in case any system errors occur.

※Added Features and Software Changes:

=====

Added:

1. The access privileges of a sub-administrator, such as the read / write access to a system setting or the browsing of log contents, now can be specifically assigned on an individual basis under System > Admin.
2. IM dialogs (search results of IM data recordings) now are available for download under Record Analysis > Services > IM.
3. The browsing of any data recordings now is logged under Status > Event Logs.

Fixed:

1. Unable to record the instant messages from some messengers due to version update.
2. Unable to record the web email service from some providers due to website revision.
3. Unable to block some applications due to version update.

AirLive Security Gateway Firmware Release_IAR-5000

✧ Important!

1. Due to a major version change, units would require a factory reset if a downgrade is performed from this version to a previous version.
2. To ensure the success of this upgrade, any user who is running a version prior to v6.07 must follow the upgrade order: v6.07 > v6.11 > v7.04 > v7.10 > v9.02.

※ Software Update Procedure:

=====

To perform the Software Update:

Step 1: Enter the web interface.

Step 2: Select "**System**" --> "**Administration**" and then select "**Software Update**".

Step 3: Click "**Browse**" to select the latest version of Software.

Step 4: Click "**OK**" to update software.

※Warning:

=====

1. Do not rename the file.
2. Do not reload the page, turn the power off or engage in any online activity during the upgrade process. This will damage the unit.
3. Do not transfer this firmware via FTP.
4. Do not update the device with the firmware of an inappropriate model.

Please test in advance, please contact us if encounter problems.