Run MU-7000AVs format tool in Vista

1. Find the Format Transfer AirLive_FT_Xp2k folders in CD
2. Select the format tool icon and click　right buttons
3. Run the "Run as administrator"