

Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
1	HP	Business 1000	OK	N/A		
2	HP	Business 1100d	OK	OK		
3	HP	Business 1200d	OK	OK		
4	HP	CLJ 1500L	OK	N/A		
5	HP	CLJ 1600	OK	N/A		
6	HP	CLJ 2600n	OK	N/A	OK	
7	HP	CLJ 2605	OK	N/A	--	
8	HP	CLJ 2700n	OK	N/A	OK	
9	HP	CLJ 2840	OK	N/A	--	
10	HP	CLJ 3000dn	OK	N/A	OK	
11	HP	CLJ 3500	OK	N/A		
12	HP	CLJ 3500N	OK	N/A		
13	HP	CLJ 3600	OK	N/A		
14	HP	CLJ 3600dn	OK	N/A		
15	HP	CLJ 3600n	OK	N/A		
16	HP	CLJ 3700	OK	OK		
17	HP	CLJ 4600	OK	N/A		
18	HP	CLJ 5500	N/A	OK		
19	HP	CLJ 5500dn	N/A	OK		
20	HP	CLJ CP1215(GDI)	NG	N/A	OK	
21	HP	CLJ CP3505	OK	N/A	OK	
22	HP	CLJ CP3525	OK	N/A	OK	
23	HP	CLJ 3000dn	OK	N/A	OK	
24	HP	CM1015MFP	OK	N/A	--	
25	HP	CM1017MFP	OK	N/A	--	
26	HP	Deskjet 1120C	OK	N/A		
27	HP	Deskjet 1125C	N/A	OK		
28	HP	Deskjet 1180C	OK	OK		
29	HP	Deskjet 3325	OK	N/A		
30	HP	Deskjet 3535	OK	N/A		
31	HP	Deskjet 3550	OK	N/A		
32	HP	Deskjet 3650(GDI)	OK	N/A	OK	
33	HP	Deskjet 3820	OK	OK		
34	HP	Deskjet 3940	OK	N/A	OK	
35	HP	Deskjet 450	OK	N/A		
36	HP	Deskjet 5160	OK	N/A		
37	HP	Deskjet 5550	OK	N/A		
38	HP	DeskJet 5652	OK	OK		

"N/A" means the MFP doesn't support the function.

"--" means the function is not tested.

*: Users have to close bi-directional.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
39	HP	DeskJet 5740	OK	N/A		
40	HP	Deskjet 6122	OK	OK		
41	HP	DeskJet 6540	OK	N/A		
42	HP	DeskJet 6840	OK	N/A		
43	HP	Deskjet 810C	OK	OK		
44	HP	DeskJet 845C	OK	N/A	OK	
45	HP	Deskjet 880C	OK	OK		
46	HP	Deskjet 882C	OK	OK		
47	HP	Deskjet 895cxi	OK	OK	OK	
48	HP	Deskjet 920C	OK	OK		
49	HP	Deskjet 9300	OK	OK		
50	HP	Deskjet 960	OK	N/A		
51	HP	Deskjet 9650	OK	OK		
52	HP	Deskjet 930cxi	OK	OK	OK	
53	HP	Deskjet 970cxi	OK	OK	OK	
54	HP	Deskjet 980	OK	N/A		
55	HP	Deskjet 990	OK	N/A		
56	HP	Deskjet D2360	OK	N/A		
57	HP	Deskjet D2460	OK	N/A	OK	
58	HP	Deskjet D2560	OK	N/A	OK	
59	HP	Deskjet D4160	OK	N/A	OK	
60	HP	Deskjet D4260	OK	N/A	OK	
61	HP	Deskjet D4360	OK	N/A	OK	
62	HP	Deskjet F2120	OK	N/A	OK	
63	HP	Deskjet F2180	OK	N/A	OK	
64	HP	Deskjet F380	OK	N/A	OK	
65	HP	Deskjet F4185	OK	N/A	OK	
66	HP	Deskjet F4280	OK	N/A	OK	
67	HP	DeskJet845C	OK	N/A	OK	
68	HP	LaserJet 1010	OK	N/A	N/A	
69	HP	LaserJet 1012	OK	N/A		
70	HP	LaserJet 1015	OK	N/A		
71	HP	LaserJet 1200	OK	OK		
72	HP	LaserJet 1220	OK	OK		
73	HP	LaserJet 1300	OK	OK		
74	HP	LaserJet 1320	OK	OK		
75	HP	LaserJet 2300	OK	N/A		
76	HP	LaserJet 2300L	OK	OK		

"N/A" means the MFP doesn't support the function.

" -- " means the function is not tested.

*: Users have to close bi-directional.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
77	HP	LaserJet 2420	OK	OK		
78	HP	LaserJet 2420dn	OK	OK		
79	HP	LaserJet 2605	OK	N/A		
80	HP	LaserJet 2700	OK	N/A		
81	HP	LaserJet 3015	OK	OK		
82	HP	LaserJet 3020	OK	OK	OK	
83	HP	LaserJet 3030	OK	OK	OK	
84	HP	LaserJet 3050	OK	N/A		
85	HP	LaserJet 3050z	OK	N/A	N/A	
86	HP	LaserJet 3055	OK	N/A	OK	
87	HP	LaserJet 3200	OK	N/A		
88	HP	LaserJet 3300	OK	OK		
89	HP	LaserJet 3330mfp	OK	OK		
90	HP	LaserJet 3380	OK	OK	N/A	
91	HP	LaserJet 4200L	N/A	OK		
92	HP	LaserJet 4350	OK	OK		
93	HP	LaserJet 4650	OK	N/A		
94	HP	LaserJet 5100LE	N/A	OK		
95	HP	LaserJet 5100SE	N/A	OK		
96	HP	LaserJet 5200L	OK	OK		
97	HP	LaserJet 5200n	OK	OK	OK	
98	HP	LaserJet J4580	OK	OK	OK	
99	HP	LaserJet M1005MFP	OK	N/A	OK	
100	HP	LaserJet P2015	OK	N/A	OK	
101	HP	OfficeJet 4110	OK	N/A		
102	HP	OfficeJet 4255	OK	N/A	OK	
103	HP	OfficeJet 4355	OK	N/A	OK	
104	HP	OfficeJet 5110	OK	OK		
105	HP	OfficeJet 5510	OK	N/A		
106	HP	OfficeJet 5610	OK	N/A	OK	
107	HP	OfficeJet 6110	OK	N/A		
108	HP	OfficeJet 6210	OK	N/A		
109	HP	OfficeJet 6310	OK	N/A	OK	
110	HP	OfficeJet 7210	OK	N/A		
111	HP	OfficeJet 7410	OK	N/A	OK	
112	HP	OfficeJet 9100	OK	N/A		
113	HP	OfficeJet 9110	OK	OK		
114	HP	OfficeJet 9120	OK	OK		

“N/A” means the MFP doesn’t support the function.

“ -- ” means the function is not tested.

*: Users have to close bi-directional.

** : Some of Lexmarks, please close bi-directional, choose “WinPrint” processor and RAW printing.

Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
115	HP	OfficeJet 9130	OK	OK		
116	HP	OfficeJet J5780	OK	N/A	OK	
117	HP	OfficeJet K7100	OK	OK	OK	
118	HP	OfficeJet K8600	OK	N/A	OK	
119	HP	OfficeJet Pro K5300	OK	N/A	OK	
120	HP	OfficeJet Pro K5400	OK	N/A		
121	HP	OfficeJet Pro K5400dn	OK	N/A	OK	
122	HP	OfficeJet Pro K850	OK	OK		
123	HP	OfficeJet Pro K850dtn	OK	OK		
124	HP	OfficeJet Pro L7380	OK	N/A	OK	
125	HP	OfficeJet Pro L7580	Ok	N/A	OK	
126	HP	OfficeJet V40	OK	N/A		
127	HP	Photosmart 145	OK	N/A		
128	HP	Photosmart 245	OK	N/A		
129	HP	Photosmart 2575	OK	N/A	OK	
130	HP	Photosmart 2610	NG	N/A	OK	Win 2000 NG
131	HP	Photosmart 2710	OK	N/A		
132	HP	Photosmart 3110	OK	N/A		
133	HP	Photosmart 325	OK	N/A		
134	HP	Photosmart 3310	OK	N/A		
135	HP	Photosmart 375	OK	N/A		
136	HP	Photosmart 7550	OK	N/A		
137	HP	Photosmart 7660	OK	N/A		
138	HP	Photosmart 7760	OK	N/A		
139	HP	Photosmart 7960	OK	N/A		
140	HP	Photosmart 8230	OK	N/A		
141	HP	Photosmart 8450	OK	N/A		
142	HP	Photosmart 8750	OK	N/A		
143	HP	Photosmart A526	OK	N/A	OK	no Win2000 Driver
144	HP	Photosmart C3180	OK	N/A	OK	
145	HP	Photosmart C4180	OK	N/A		
146	HP	Photosmart C4280	OK	N/A	OK	
147	HP	Photosmart C4385	OK	N/A	OK	
148	HP	Photosmart C4480	OK	N/A	OK	no Win2000 Driver
149	HP	Photosmart C5180	OK	N/A	Ok	
150	HP	Photosmart C5280	OK	N/A	Ok	

"N/A" means the MFP doesn't support the function.

" -- " means the function is not tested.

*: Users have to close bi-directional.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
151	HP	Photosmart C5380	OK	N/A	OK	no Win2000 Driver
152	HP	Photosmart C6180	OK	N/A	Ok	
153	HP	Photosmart C6280	OK	N/A	Ok	
154	HP	Photosmart C7180	Ok	N/A	OK	
155	HP	Photosmart C7280	OK	N/A	OK	
156	HP	Photosmart C8180	OK	N/A	OK	
157	HP	Photosmart D5160	OK	N/A	OK	
158	HP	Photosmart D5360	OK	N/A	OK	
159	HP	Photosmart D5460	OK	N/A	OK	
160	HP	Photosmart D7160	OK	N/A		
161	HP	Photosmart D7360	OK	N/A	OK	
162	HP	PSC 1110	OK	N/A		
163	HP	PSC 1210	OK	N/A	OK	
164	HP	PSC 1315	OK	N/A	OK	
165	HP	PSC 1350	OK	N/A		
166	HP	PSC 1410	OK	N/A	OK	
167	HP	PSC 1510	OK	N/A	OK	
168	HP	PSC 1610	OK	N/A	OK	
169	HP	PSC 2110	OK	N/A	OK	
170	HP	PSC 2210	OK	N/A	OK	
171	HP	PSC 2310	OK	N/A	OK	
172	HP	PSC 2355	OK	N/A	OK	
173	HP	PSC 2410	OK	N/A	OK	
174	HP	PSC 2510	OK	N/A	OK	
175	HP	PSC 4110	OK	N/A		
176	HP	PSC 750	OK	N/A		
177	Epson	Aculaser C1100	OK	OK	OK	
178	Epson	Aculaser C1900	OK	OK		
179	Epson	Aculaser C3800N	OK	N/A	OK	
180	Epson	Aculaser C4000	OK	OK		
181	Epson	Aculaser C4100	OK	OK		
182	Epson	Aculaser C8600	OK	OK		
183	Epson	DLQ-3500C	OK	OK		
184	Epson	EC-01	OK	N/A	OK	
185	Epson	EPL-5900L	OK	OK	OK(Vista32)	***No Vista 64
186	Epson	EPL-6100	OK	OK		
187	Epson	EPL-6200	OK	OK	OK(Vista32)	No Vista64

"N/A" means the MFP doesn't support the function.

" -- " means the function is not tested.

*: Users have to close bi-directional.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
188	Epson	EPL-N2500	OK	OK	OK	
189	Epson	EPL-N2750	N/A	OK		
190	Epson	EPL-N3000	OK	OK	OK	
191	Epson	LQ-2080C	N/A	OK		
192	Epson	LQ-300+	N/A	OK		
193	Epson	LQ-300+II	OK	N/A	OK(Vista32)	No Vista64
194	Epson	LQ-680C	N/A	OK	N/A	
195	Epson	Picture Mate PM210	OK	N/A	OK	
196	Epson	Stylus C4100	OK	N/A	OK	
197	Epson	Stylus C43UX	OK	N/A		
198	Epson	Stylus C45	OK	N/A	OK	
199	Epson	Stylus C59	OK	N/A	OK	no Vista64
200	Epson	Stylus C63	OK	N/A		
201	Epson	Stylus C83	OK	N/A		
202	Epson	Stylus C90	OK	N/A	OK	
203	Epson	Stylus C110	OK	N/A	OK	
204	Epson	Stylus COLOR 1160	OK	N/A		
205	Epson	Stylus COLOR 880	OK	--		
206	Epson	Stylus CX1500	OK	N/A		
207	Epson	Stylus CX3100	OK	N/A		
208	Epson	Stylus CX3700	OK	N/A	OK	
209	Epson	Stylus CX3900	OK	N/A	OK	
210	Epson	Stylus CX4100	OK	N/A	OK	
211	Epson	Stylus CX4700	OK	N/A	OK	
212	Epson	Stylus CX4900	OK	N/A	OK	
213	Epson	Stylus CX5100	OK	N/A		
214	Epson	Stylus CX5300	OK	N/A		
215	Epson	Stylus CX5500	OK	N/A	OK	
216	Epson	Stylus CX5505	OK	N/A	OK	
217	Epson	Stylus CX5900	OK	N/A	OK	
218	Epson	Stylus CX6900F	OK	N/A	OK	
219	Epson	Stylus CX7300	OK	N/A	OK	
220	Epson	Stylus CX8300	OK	N/A	OK	
221	Epson	Stylus CX9300F	OK	N/A	OK	
222	Epson	Stylus CX9400F	OK	N/A	OK	
223	Epson	Stylus TX200	OK	N/A	OK	
224	Epson	Stylus PHOTO 1390	OK	N/A	OK	
225	Epson	Stylus PHOTO 2100	OK	OK		

"N/A" means the MFP doesn't support the function.

"--" means the function is not tested.

*: Users have to close bi-directional.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
226	Epson	Stylus PHOTO 830U	OK	N/A		
227	Epson	Stylus PHOTO 750	OK	x	OK	
228	Epson	Stylus PHOTO 935	OK	N/A		
229	Epson	Stylus PHOTO R210	OK	N/A		
230	Epson	Stylus PHOTO R230	OK	N/A		
231	Epson	Stylus PHOTO R270	OK	N/A	OK	
232	Epson	Stylus PHOTO R290	OK	N/A	OK	
233	Epson	Stylus PHOTO R310	OK	N/A	OK	
234	Epson	Stylus PHOTO R1900	OK	N/A	OK	
235	Epson	Stylus PHOTO RX430	OK	N/A		
236	Epson	Stylus PHOTO RX510	OK	N/A		
237	Epson	Stylus PHOTO RX530	OK	N/A	OK	
238	Epson	Stylus PHOTO RX590	OK	N/A	OK	
239	Epson	Stylus PHOTO RX630	OK	N/A		
240	Epson	Stylus PHOTO RX650	OK	N/A	OK	
241	Epson	Stylus PHOTO RX690	OK	N/A	OK	
242	Canon	C350	OK	N/A		
243	Canon	i255	OK	N/A		
244	Canon	i320	OK	N/A		
245	Canon	i355	OK	N/A		
246	Canon	i450	OK	N/A		
247	Canon	i455	OK	N/A		
248	Canon	i475D	OK	N/A		
249	Canon	i560	OK	OK		
250	Canon	i6100	OK	OK		
251	Canon	i6500	OK	OK		
252	Canon	i865	OK	OK		
253	Canon	i905D	OK	N/A	OK	
254	Canon	i9100	OK	N/A		
255	Canon	i9950D	OK	N/A		
256	Canon	iC D380	OK	N/A		
257	Canon	iP100	OK	N/A	OK	
258	Canon	iP1000	OK	N/A		
259	Canon	iP1200	OK	N/A	OK	
260	Canon	iP1500	OK	N/A		
261	Canon	iP1880	OK	N/A	OK	
262	Canon	iP1980	OK	N/A	OK	
263	Canon	iP2000	OK	N/A		

"N/A" means the MFP doesn't support the function.

" -- " means the function is not tested.

*: Users have to close bi-directional.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
264	Canon	iP3000	OK	N/A		
265	Canon	iP3300	OK	N/A	OK	
266	Canon	iP3500	OK	N/A	OK	
267	Canon	iP3680	OK	N/A	OK	
268	Canon	iP4000	OK	OK		
269	Canon	iP4200	OK	N/A	OK	
270	Canon	iP4300	OK	N/A	OK	
271	Canon	iP4500	OK	N/A	OK	
272	Canon	iP4680	OK	N/A	OK	
273	Canon	iP5000	OK	N/A	OK	
274	Canon	iP6000D	OK	N/A		
275	Canon	iP8500D	OK	N/A		
276	Canon	iR 2010	OK	OK		
277	Canon	iR 6000	N/A	OK		
278	Canon	iR 8500	N/A	OK		
279	Canon	iX4000	OK	N/A	OK	
280	Canon	iX5000	OK	N/A		
281	Canon	PIXMA MP110	OK	N/A		
282	Canon	PIXMA MP130	OK	N/A	OK	
283	Canon	PIXMA MP150	OK	N/A		
284	Canon	PIXMA MP160	OK	N/A		
285	Canon	PIXMA MP170	OK	N/A		
286	Canon	PIXMA MP180	OK	N/A	Ok	
287	Canon	PIXMA MP198	OK	N/A	Ok	
288	Canon	PIXMA MP268	OK	N/A	Ok	
289	Canon	PIXMA MP450	OK	N/A	OK	
290	Canon	PIXMA MP486	OK	N/A	Ok	
291	Canon	PIXMA MP510	OK	N/A		
292	Canon	PIXMA MP520	OK	N/A		
293	Canon	PIXMA MP545	OK	N/A	OK	
294	Canon	PIXMA MP638	OK	N/A	OK	
295	Canon	PIXMA MP700	OK	N/A		
296	Canon	PIXMA MP730	OK	N/A		
297	Canon	PIXMA MP780	OK	N/A		
298	Canon	Pro 9000	OK	N/A	OK	
299	Canon	S200SPx	OK	N/A		
300	Lexmark	C510	OK	OK		
301	Lexmark	E230	OK	OK		

"N/A" means the MFP doesn't support the function.

" -- " means the function is not tested.

*: Users have to close bi-directional.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
302	Lexmark	X3550	OK	N/A	OK	
303	Lexmark	X4550	OK	N/A	OK	
304	Lexmark	X6170	OK	N/A	OK(Vista 64)	No Vista32
305	Lexmark	X1185	OK	N/A	OK	**
306	Lexmark	X1195	OK	N/A	OK	**
307	Lexmark	Z1420	--	N/A	OK	
308	Lexmark	Z603	OK	N/A	OK	**
309	Lexmark	Z615	OK	N/A		**
310	Lexmark	Z645	OK	N/A	OK	**
311	Lexmark	Z705	OK	N/A		**
312	Lexmark	Z810	OK	N/A		**
313	Lexmark	Z816	OK	N/A		**
314	Konica Minolta	Bizhub 210	OK	N/A	OK	no Vista64
315	Konica Minolta	Magicolor 2400W	OK	N/A	OK	
316	Konica Minolta	Magicolor 2480MF	OK	N/A	OK(Vista 32)	***No Vista64
317	Konica Minolta	Magicolor 5550	OK	N/A		
318	Konica Minolta	Magicolor 5570	OK	N/A		
319	Konica Minolta	PagePro 1380MF	OK	N/A	OK	No Vista 64
320	Dell	944	OK	N/A		
321	Dell	Mono LaserMFP1125	OK	N/A	OK	No Win2000
322	Brother	HL-2070	OK	N/A		
323	Brother	HL-5240	OK	N/A		
324	Brother	MFC-210C	OK	N/A		
325	Brother	MFC-215C	OK	N/A		
326	Brother	MFC-2820	OK	N/A		
327	Brother	MFC-3240C	OK	N/A		
328	Brother	MFC-420CN	OK	N/A		
329	Brother	MFC-425CN	OK	N/A		
330	Brother	MFC-4800J	OK	N/A		
331	Brother	MFC-7420	OK	N/A		
332	Brother	MFC-7820N	OK	N/A		
333	Brother	MFC-8840D	OK	N/A		
334	Kyocera	FS-920	OK	OK	OK	
335	Kyocera	FS-1030D	OK	OK	OK	
336	Kyocera	FS-1100	OK	N/A	OK	
337	SAMSUNG	CLX-2160N	OK	N/A	OK	
338	SAMSUNG	ML-1520LP	OK	N/A		
339	SAMSUNG	ML-1610	OK	N/A	OK	

"N/A" means the MFP doesn't support the function.

" -- " means the function is not tested.

*: Users have to close bi-directional.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.

Print Server Compatible Tested

NO.	Brand Name	MFP Model	USB Port	Parallel Port	Vista32/64	Remark
340	SAMSUNG	ML-1740	OK	OK		
341	SAMSUNG	ML-2010(GDI)	OK	N/A	OK	
342	SAMSUNG	SCX-4100	OK	OK		
343	SAMSUNG	SCX-4200	OK	OK		
344	SAMSUNG	SCX-4521F	OK	OK	OK	
345	SAMSUNG	SCX-4720F	OK	OK	OK	
346	SAMSUNG	SF-565P	OK	OK	OK	
347	SHARP	AR-M236	OK	N/A	N/A	

"N/A" means the MFP doesn't support the function.

"--" means the function is not tested.

*: Users have to close bi-directional.

** : Some of Lexmarks, please close bi-directional, choose "WinPrint" processor and RAW printing.