

V7.10:

MD5 Checksums: c7f097b33adac9f07432cf735c49f603

※Note: Verify the MD5 checksum of the downloaded file with a MD5 sum checker (e.g. MD5summer) to see if it matches the one provided above.

Firmware Fixed :

1. Unable to record QQ messenger messages, Yahoo web email service, the instant messages originated from an IR plug-in user with a DHCP-distributed address and the message exchanges between MSN and Yahoo!.
2. The activation of Skype-blocking feature
3. The application blocking patterns used have been optimized.

Important!

1. System configuration import / export does not support different firmware version. Please back up the system configuration before upgrading the firmware.
2. To ensure the success of this upgrade, any user who is running a version prior to v6.07 must follow the upgrade order: v6.07 > v6.11 > v7.04 > v7.10